

0009

CO-OP MINING COMPANY

ACT/015/025-93A

P.O. Box 1245
Huntington, Utah 84528.



(801) 381-5238
Coal Sales (801) 381-5777

Copy FAM

January 14, 1993

Pamela Grubaugh-Littig
Permit Supervisor
Utah Division of Oil, Gas & Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RECEIVED

JAN 19 1993

Ms. Grubaugh-littig,

DIVISION OF
OIL GAS & MINING

**RE: Division Order and Technical Deficiency, Bear Canyon Mine,
Co-Op Mining Company, ACT/015/025-90A. Emery County, Utah**

Enclosed is a response to the remaining deficiency on the above-reference Division Order. The deficiency stated that the road leading to the Ball Park area was removed from the permit area and should be included in the Bear Canyon permit area.

Co-Op originally added the Ball Park area in order to store substitute topsoil material which Co-Op purchased to alleviate a deficiency in onsite topsoil material. Prior to this action, the Ball Park and road, which was the access to the recreation area owned by C.O.P. Development Company, already existed. No work was performed on the road relating to mining activities. The original maps to which the Ball Park area was added to the permit area did not include the road in the permit area. (The original Plate 2-4, dated 5/31/85, latest revision date 10/15/90, included only the Ball Park and not the road.) In 1991, Plates 2-4, 3-2, 7-1 and 8-5 were regenerated from an aerial survey which Co-Op had performed in response to Division Order 90A. When the maps were submitted, the access road to the Ball Park was erroneously added during the review process and was not approved. The approved permit description never included the access road to the Ball Park. During subsequent reviews of technical deficiencies related to this same Division Order, it was discovered that the access road had been erroneously added to the permit area. Since the original addition was never approved, the maps were revised to exclude the road at that time.

Page 2
DOGM
14 January 1993

In the latest review of technical deficiencies relating to this same Division Order (90A), in-place materials were approved for use as substitute topsoil, eliminating the need for the substitute material stored on the Ball Park. Since the material is no longer needed, the enclosed submittal proposes to remove the Ball Park from the permit area.

If you have any questions, call Charles Reynolds at (801) 381-2450.

Thank You,

A handwritten signature in cursive script, appearing to read "Wendell Owen".

Wendell Owen
Resident Agent

WJO
cr
ENCLOSURE(S)